

- 1. REF. "A" REFLECTS THAT #2 LOX CONVERTER ON 053
 WAS CHANGED FOR LEAK DISCOVERED DURING PREFLIGHT PRIOR TO
 MISSION C-191-C. REF. "B" STATED THAT YOU HAD JUST RECEIVED
 A LOX CONVERTER TO INSTALL IN 053 WHICH PREVENTED CANNIBALIZATION
 OF 051, 9 JUNE 71. REQUEST YOU ADVISE HOW THE ADDITIONAL LOX
 CONVERTER WAS ACQUIRED. REQUEST THE NUMBER OF LOX CONVERTERS
 ON HAND SERVICEABLE AND REPARABLE.
- 2. PLS ADVISE THE LOX SYSTEM PRESSURE READINGS IN SYSTEMS
 1 AND 2 AFTER COMPLETION OF MISSION C-191-C. REF. "C" INDICATES
 THAT BOTH #1 AND #2 SYSTEMS INDICATE LOW PRESSURE.

25X1

